## Perez, Susan

From: Cpt. William Cooper [wcooper@txtreasure.com]

Sent: Saturday, September 07, 2002 4:12 PM

To: vsp@cdc.gov

Cc: Don Carter; claude can

Subject: texas treasure 1-cas-(098/05/2002)

- 1.Complete log as per suggestions.Seperate AM/PM cruises.
- 2.Renew shore line to reach ship in solid pipe rather than hose, short hose store in box provided.
- 3. Tank chlorination is kept but not shown to Inspector. Seperate log with USPH paperwork will be kept.
- 4. Fit back flow preventions as suggested soonest.
- 5. The shore water test although for 200 is the latest supplied by County, new one due out on November.
- 6.Refrigerator to be repaired soonest.
- 7.Cut off and blank the pipe.
- 8.Look into better maintenance of lids.
- 9.Recover wall, had just done work behind this wall and covering was damaged at the time.
- 10.Check cleaning process.
- 11. Have damage repaired.
- 12.make sure more supervision.
- 13. Replace missing paper toweldispenser, place sign.
- 14. New thermometers to supply and use.
- 15. Fit blast freezer whenever possible, meanwhile for Pastry Chef to be more ware of the problem.

More comprehensive record of temperatures in refridges to be maintained.

- 16.Label bins
- 17.Plumber has fixed.
- 18.stack on edges not faces in future.
- 19.To order and fit data plates.
- 20.Check vent drain so when washing down vessel no water comes into vent areas.
- 21. Items to be made operational when spare parts arrive.
- 22. Design fault, can try and keep dry.
- 23.Build design.
- 24. Fill in any gaps as applicable.
- 25.As above.
- 26. This is varnished.
- 27. Dining Room Staff to be made aware and have these items stacked upside down for draining/drying.
- 28.Look at how to fit some form of protection.
- 29. Repair when parts arrive.
- 30.Lift supply lines off decks.
- 31.Replace missing bulbs.
- 32. Remove mop/bucket from bar area.
- 33.Crew to be reminded to place bread under sneeze guard.

I am,

Yours faithfully

Captain William C.Cooper.Master.